DATA SHEET



Latrobe, PA 15650-0031 USA

Issue 1

LSS[™] O1 Tool Steel (ASTM O1)


Typical Composition

С	Mn	Si	Cr	W
0.94	1.20	0.30	0.50	0.50

LSS O1 tool steel is the original oil-hardening, "non-shrinking" tool steel that can be hardened to the Rockwell C 65 range from a low austenitizing temperature. LSS O1 is a general-purpose tool steel that is typically used in applications where alloy steels cannot provide sufficient hardness, strength, and wear resistance.

Where greater dimensional stability in heat treatment or improved wear resistance is required, tool steels with higher alloy contents, such as A2 or D2 should be considered.

Relative Properties



Physical Properties

Density: 0.283 lb/in³ (7833 kg/m³)

Specific Gravity: 7.83

Modulus of Elasticity: 31x106 psi (214 GPa)

Machinability: 85 -90% of a 1% carbon steel

Coefficient of Thermal Expansion: (at 63-64 HRC)

Temperature, °F	in/in °Fx10 ⁻⁶	Temperature, °C	mm/mm °Cx10 ⁻⁶
100 - 500	5.96	38 - 260	10.73
100 - 800	7.14	38 - 427	12.85
100 - 1000	7.84	38 - 538	14.11
100 - 1200	8.02	21 - 649	14.44

LSS™ O1 HEAT TREATING INSTRUCTIONS

(See Tech-Topics Bulletin 102 for a more thorough explanation of heat treating.)

HARDENING:

Critical Temperatures:

Ac1: 1350°F (732°C) Ac3: 1400°F (760°C) Ar1: 1295°F (703°C) Ar3: 1240°F (671°C)

Preheating: Heat at a rate not exceeding 400°F per hour (222°C per hour) to 1200-1300°F (649-704°C) and equalize.

Austenitizing (High Heat): Heat slowly from the preheat to 1475-1500°F (802-816C)

Soak for 30 minutes for the first inch (25.4 mm) of thickness, plus 15 minutes for each additional inch (25.4 mm).

Quenching: Oil quench to a temperature no lower than 150-125°F (66-51°C).

Note: O1 is somewhat prone to quench cracking, especially if there are significant changes in section thickness and sharp internal corners. The oil quenching should be performed so that the heat removal is as uniform as possible in all areas of the part being quenched. Be sure to remove the part from the oil before the temperature drops to ambient temperature. Hot oil at a temperature of 300 to 400°F (149-204°C) is recommended.

Tempering: Temper immediately after quenching. Do not allow the part to cool below 125°F (51°C). The typical tempering range is 350 - 400°F (177 - 204°C). Hold at temperature for 1 hour per inch (25.4 mm) of thickness, 2 hours minimum, then air cool to ambient temperature.


To minimize internal stresses in cross sections greater than 3 inches (76.2 mm) and to improve stability in parts that will be EDM'd after heat treatment, a soaking time of 4 to 6 hours at the tempering temperature is strongly recommended.

ANNEALING: Annealing must be performed after hot working and before rehardening.

Heat at a rate not exceeding 400°F per hour (222°C per hour) to 1425 -1450°F (802-816°C), and hold at temperature for 1 hour per inch (25.4mm) of maximum thickness; 2 hours minimum. Then cool slowly with the furnace at a rate not exceeding 50°F per hour (28°C per hour) to 1000°F (538°C). Continue cooling to ambient temperature in the furnace or in air. The resultant hardness should be a maximum of 212 HBW.

HEAT TREATMENT RESPONSE

As Air Cooled from	HRC
1425°F (774°C), 30 minutes	62
1450°F (788°C), 30 minutes	64
1475°F (802°C), 30 minutes	65
1500°F (816°C), 30 minutes	65
1600°F (871°C), 30 minutes	64



Cryogenic Treatment: Refrigeration treatments should typically be performed after the temper, and must be followed by a second temper.



WEB: www.latrobesteel.com

The data presented herein are typical values, and do not warrant suitability for any specific application or use of this material. Normal variations in the chemical composition, the size of the product, and heat treatment parameters may result in different values for the various physical and mechanical properties.

Latrobe, PA Phone: 724-537-7711 **Vienna, OH** Phone: 800-321-6446 FAX: 724-532-6316 FAX: 330-609-2054

NOH Phone: 800-321-6446 Marlborough, MA Phone: 800-444-4447 FAX: 330-609-2054 FAX: 508-481-6581